




VIEW FROM OUTSIDE OF MOTOR AT SWITCH END.



## LINE LEADS



SPEED	L1	L2	L3	JOIN	SEPARATE
HIGH	T6	T4	T5	(T1,T2,T3)	
LOW	T1	T2	T3		(T4),(T5), (T6)

				TOLERANCES UNLESS SPECIFIED			ELECTRIC MOTORS GEARMOTORS AND DRIVES		DRAWN DLL 10/19/77	
				DEC.	INCHES				CHK RPB 10/28/77	
				.X	±.1				APPD JCW 10/31/77	
				.XX	±.01				SCALE 1=1	
03	SPEED WAS VOLTAGE	RLW 6/23/04		.XXX	±.005	TITLE EXT. WIRING DIAGRAMS 3 PHASE W/O PROTECTOR		REF W-T8(4-8)1		
02	REDRAWN TO CAD	DBT 5/30/97		.XXXX	±.0005			MAT'L.DECAL: 004183 2SPEED/1WINDING/CONSTANT TORQUE		FMF 184T17FB9
NO.	REVISION	BY & DATE	CHK	ANG	±1/2"	FINISH		PREV		
THIS DRAWING IN DESIGN AND DETAIL IS OUR PROPERTY AND MUST NOT BE USED EXCEPT IN CONNECTION WITH OUR WORK ALL RIGHTS OF DESIGN AND INVENTION ARE RESERVED THIS IS AN ELECTRONICALLY GENERATED DOCUMENT - DO NOT SCALE THIS PRINT			RFP 10/31/77		CAD FILE 00514801		SIZE	DRAWING NO.		REV.
			DIST				A	005148-01		03