

# Tech Bulletin

## Hand Crank to Explosion Proof Motor Requirements

---

### Hand Crank to Explosion Proof Motor - Kit #S600781 CA33112 L to EA33112 L10AX

Qty.	Part #	Description
1	260430	Drive Motor
1	260456	Spacer
1	260406	Drive Chain
1	260407	Spool Gear
1	260434	Motor Gear
4	300039	Washer
4	S2-52	Hex Cap Screw
4	S44-3	Machine Screw
6	S27-112	Flat Cap Socket Screw
6	S79-3	Flange Nut
6	260410	Gear Spacer

### Hand Crank to Explosion Proof Motor - Kit #S600782 CA33112 L to EA33112 L12DX

Qty.	Part #	Description
1	260583	Drive Motor
1	260456	Spacer
1	260406	Drive Chain
1	260407	Spool Gear
1	260434	Motor Gear
4	300039	Washer
4	S2-52	Hex Cap Screw
4	S44-3	Machine Screw
6	S27-112	Flat Cap Socket Screw
6	S79-3	Flange Nut
6	260410	Gear Spacer

Form # TB0013 Rev: 5/2012

**Hand Crank to Explosion Proof Motor - Kit #S600783**

CA33112 L to EA33112 L24DX

<b>Qty.</b>	<b>Part #</b>	<b>Description</b>
1	260626	Drive Motor
1	260456	Spacer
1	260406	Drive Chain
1	260407	Spool Gear
1	260434	Motor Gear
4	300039	Washer
4	S2-52	Hex Cap Screw
4	S44-3	Machine Screw
6	S27-112	Flat Cap Socket Screw
6	S79-3	Flange Nut
6	260410	Gear Spacer